

Date received: 16-03-10

Date of issue: 30-03-10

Report consists of 1 attached sheet.

Defects before testing: None

Sample name: Chair Art. Gamilla

SEDIE FRIULI DI FORNASARIG S.R.L.
VIA SAN GIOVANNI, 45
33044 MANZANO (UD)
ITALY**TEST REPORT N° 114334**

Overall dimensions: 470 x 520 x 800 (h) mm (extended uncertainty = 5 mm)

List performed tests

1. Seat and back fatigue test EN 1728:2000



This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.



Managing Director
Dr. Andrea Giavon

TEST REPORT

114334 / 1

Date received: 16-03-10
Date of test: 16-03-10
Date of issue: 30-03-10



Sample name: Chair Art. Camilla

SEDIE FRIULI DI FORNASARIG S.R.L.
VIA SAN GIOVANNI, 45
33044 MANZANO (UD)
ITALY

Seat and back fatigue test EN 1728:2000

Seat and back fatigue test, clause 6.7

Test results:

Seat force N	Back force N	Number of cycles	Remarks
1.000	300	200.000	No defects

Note:

The test has been carried out according to table 1 of EN 15373:2007, level 3 - severe.

NOTE: As requested by the customer, the sample has been tested without storing for one week in indoor ambient conditions.

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.



Managing Director
Dr. Andrea Giavon

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer.